

EQUIPMENT CHECKLIST

EQUIPMENT	INSPECT	BASIC THINGS TO LOOK FOR
PANTS	Condition	No tears, loose threads &/or dangling belts/straps. Inside zippers done up and working.
STICK		Plug is in butt end of the stick (top).Blade has no sharp edges, breakages
HELMET	Condition	 Must have visible CSA label, snug chin strap, ear guards, be decal/tape free & not painted. No cracks in shell or padding.
FACEMASK	Condition	 No metal bars broken on cages Tight screws and if replacements, NOT too long. Straps snug with stretch in elastic Clips in place. NO cracks in plastic watch for rust at wire seams
GLOVES	Condition	 High enough so covers wrist. Firm fingers, thumb and back padding Palms soft and pliable. NO holes near fingers or in palm larger than a quarter) No loose threads
NECKGUARD	Condition	 Completely covers neck Fits snug enough to avoid exposing parts of neck and upper chest MUST have BNQ certification, be free of fabic cuts Velcro strap NOT worn and in good working order Must not be altered in any way Rips or tears should be sewn. No tape wrapped around neckguard